



Lenord & Bauer Gel 823XXX

- Errors introduced under specific environmental conditions (High Humidity)
- Solutions: Conformal coating now added as standard!



- Prone to Communication and timeout, noise and transient signal issues
- Solution: Circuit Enhancements use of Military spec Opto-couplers
- Improved Protection and higher electrical power rating